

APPENDIX 1

**Region 9 Enforcement Division
75 Hawthorne Street
San Francisco, CA 94105**


PHILLIPS 66 WILMINGTON PHOTOGRAPH LOG



Photograph 1. IMG_0019.jpg - Debris around sump at heat exchange bundle cleaning pad.



Photograph 2. IMG0250.jpg - Debris outside of secondary containment of heat exchange bundle cleaning pad secondary containment.



Photograph 3. IMG_0011.jpg - Gouges in heat exchange bundle cleaning pad pavement.



Photograph 4. IMG_0018.jpg - Gouges in heat exchange bundle cleaning pad pavement.



Photograph 5. IMGP0241.jpg - Gouges in heat exchange bundle cleaning pad pavement.



Photograph 6. IMGP0240.jpg - Liquid in heat exchange bundle cleaning pad sump.



Photograph 7. IMG_0028.jpg - Oily water and debris in the oil truck unloading area adjacent to the hazardous waste accumulation area.



Photograph 8. IMG_0044.jpg - Opened 5-gallon bucket at the vacuum truck unloading area adjacent to the ORU.



Photograph 9. IMGP0273. Baker tank used to store hazardous waste from Tank cleanout.



Photograph 10. IMGP0281.jpg - Water leaking from a pipe into the closed oil recovery basin.



Photograph 11. IMGP0278.jpg - Water and debris in closed oil recovery basin.



Photograph 12. IMG_0005.jpg - Debris inside closed oil recovery basin.



Photograph 13. IMG_0004.jpg - Tear in lining of closed oil recovery basin.



Photograph 13. IMG0294 - Sump pumping liquid out of Selenium plant roll-off bin for filter cakes.



Photograph 14. IMGP0296.jpg - Liquid inside secondary containment of Selenium Plant Roll-off bin secondary containment.




Photograph 145. IMGP0297.jpg - Liquid inside secondary containment of Selenium Plant Roll-off bin secondary containment.



Photograph 156. IMGP0315.jpg - Sand blast grit on the ground in the bead blast room of the maintenance area.



Photograph 167. IMGP0316.jpg - Sand blast grit on the ground in the bead blast room of the maintenance area.



Photograph18. IMGP0314.jpg - No accumulation start date on 55-gallon container of sand blast grit in the bead blast room of the maintenance area.



Photograph 19. IMGP0319.jpg - Empty aerosol cans in flammable locker in paint room of maintenance area.



Photograph 17. IMGP0322. Unknown liquid found in Paint Room of Maintenance Area.



Photograph 18. IMGP0326 - 5-gallon bucket with contaminated materials and empty aerosol cans.



Photograph 19. IMGP0327 - 5-gallon bucket with contaminated materials and empty aerosol cans.



Photograph 20. IMGP0302. Oily contaminated debris found in non-haz trash can.